

January 19, 2024

Second Bayshore Condominium Association, Inc C/O: Casey Management Attn: Bridget Spence

Bspence@caseymanagement.com

RE: Second Bayshore Condominium Association, Inc. 1800 Restful Dr., Bradenton, FL. 34207 Buildings A – O (Fifteen (15) buildings)

Munyan to provide skilled labor and materials for coating removal and replacement on steel posts at Second Bayshore Condominiums.

Scope of work:

- 1. Perform 100% coatings removal on all steel posts both on the front and rear elevation (front stairs and rear lanais), for purposes of detailed inspection by Engineer. This will require the removal of enclosed lanai siding or soffit on the underside of the lanai. Note: The bottom vinyl siding/soffit(s) on the lanais will not be reinstalled.
- 2. Paint coatings must be stripped down to bare steel from top to bottom on the posts. This includes attached steel base plates, weld points, and tabs.
- 3. Once coatings have been exposed, Engineer will inspect and determine need for steel repair or replacement. Posts needing repair or replacement will be flagged so that Contractor or Association can get welder to repair or replace steel.
- 4. Detailed inspection of wood framing supporting rear lanais. Perform wood framing repairs as needed. Owner installed enclosures are to be preserved in place.
- 5. This will take place on all 15 buildings, A through O. Close coordination will be required with the Engineer and Association.



Signature: